

RECEIVING INSPECTION REPORT

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080162-46

2961 E. COLORADO ST., PASADENA, CALIF.

RECEIVED FROM

DATE REC'D. 4-6-57

P.O. NO. 6544

VENDOR PACKING SLIP NO. 5874



CHARGE TO

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O ACCT. OR R W.O. NO.	S.O. NO.
322	00000	W-106	0	23					

QUANTITY RECEIVED

DRAWING NO. AND DESCRIPTION

QUANTITY
ACCEPTED REJECTED

REMARKS

4 730126-26 Relay Time Delay 3 Sec., 3V
REV-01-NC-2B

4
MC 38

Stocked

REJECTS RETURNED
ON SHIP. MEMO NO.

RECEIVED BY

HMC-106

INSPECTED BY

RPE

DATE

4-6-57

RECEIVED FROM

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2961 E. COLORADO ST., PASADENA, CALIF.

No. 11817

CHARGE TO
QUANTITY RECEIVED

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O ACCT. OR R W.O. NO.	S.O. NO.
322	00000	NOTE							

DRAWING NO. AND DESCRIPTION

QUANTITY
ACCEPTED REJECTED

REMARKS

16 730163-121 1M Connector, 4U31021-20-77
(322-00000-118-0-23-1)

16
MC 38

Stocked

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080162-4

RECEIVED BY

INSPECTED BY

RPE

DATE 4-6-57

REJECTS RETURNED

HMC-106